Projection

For a quick way to rotate the assembly into a top view, side view, front view, etc (including a handful of ISO views) the "Projection" command button works very well.

Select the "Projection" command button and a group of selections will appear.

Select the view you wish to view.

Select the "Projection" button one more time to remove the command list from the window.