

## PickPoints - Arc

This thread covers creating a PickPoint on an arc.

Please Note: The tangent ends and the center of the arc automatically have part PickPoints (cyan in color)


Step 1) Select the "**PickPoint**" tab and the "Arc" tab.

Step 2) Select the "**Select Arc**" command button.

Step 3) Select the "**PickPoint**" which represents the bend to place the new PickPoint.

Step 4) Enter in the "**Sweep Angle**" or number of degrees down the arc from the 1st tangent side of the arc.

Step 5) Select the "**Apply**" command button.



Note: The numbers of degrees for the entire arc is displayed above the "Sweep Angle". 0 (zero) degrees is on the arc end which is the start end. The start end was determined by the direction of the part creation.