

Projection

This thread covers the "Projection" command button.


For a quick way to rotate the assembly into a top view, side view, front view, etc (including a handful of ISO views) the "Projection" command button works very well.

Select the "Projection" command button and a group of selections will appear.

Select the view you wish to view.

Select the "Projection" button one more time to remove the command list from the window.

WARNING: Many users have selected the "Close" button thinking it would close the "Projection" selects only to find that they were closing their assembly.



Select the "Shade" command if you desire

