


## PickPoints: The Arc Tab


---

If you need a pick point created at a certain point on a bend, you may want to use the "Arc" tab located on the "PickPoints" tab.



For this example we're using a single part with a 90 degree bend.

1) Click the "**Select Arc**" button, click on a bend, then enter a value. Zero is the end of a bend closest to the start of your part and 90 is the end closest to the end of your part. We will enter a value of "**20**", and you can now see a new pick point located on the bend.



2) Click the "Apply" button to set the pickpoint.