

## Creating a flat dxf file from a bent part

---

Create your part



After creating your part select the "Model" drop down at the bottom of the screen and change it to "Flat".



Select the "Display" button in the upper right hand corner. Select the "Features" button on the panel. Uncheck the Flat Layout features; "Bend Lines" and "Tangent Lines"



Select "File", "Export", "DXF".



In some cases bend lines maybe left over. Use the same procedure as above and trim/break/delete the extra lines from the "Flat" model.



Notice there are extra lines.



Trim/break/delete the extra lines.