

Dial Level use for Rotation

We have ran into this issue a couple of times.

On some Dial Levels they have a different graduation on one side vs the other side. Specifically one side has a graduation of 1 degree and the other side has a graduation of 2 degrees.

