


Problem with "Single 4"



On some releases the logic for this template was incorrect. The bottom horizontal dimension was recognized as the distance from the left end of the part to the apex of the bend and not the right end of the part to the apex of the bend as drawn.

Please goto the template download window for an updated template list and the fix.
http://www.2020softwaresolutions.com/new_templates.htm