Changing the Color of a Part

Select the "Parts" tab.

Select the Color Cell of the part you wish to change.

Create & Edit Parts	Assembly Set	tings	
Part Name	Die	Material	Color
11143 HANDRAIL 1		2.0	
Custom Part - 1		2.0	8
Custom Part - 1		2.0	
•			Þ.

Select the color in the color window. Press "OK".

Color			x
Basic colors:			
		Hue: 160	Red: 0
		Sat: 0	Green: 0
Define Custom Colors >>	Color Solid	Lum: 0	Blue: 0
OK Cancel	A	dd to Custom	Colors

Trick:

Click the "Change Part Color" button. Choose a color. Click the "Select {Part(s)" button and click directly on a pickpoint on a part to change its color to the selected color.

Create & Edit Parts	Assembly Sett	tings		_
Part Name	Die	Material	Color I	1
11143 HANDRAIL 1		2.0 -	1	
Custom Part - 1		2.0	8	
Custom Part - 1		2.0	8	
Change Part Color	III Select Part(s		► Expand	
	۲ \	Select a p	Dart to c	:hange i