


Moving a Part


This section will show how to move a part in Assembly.

In our example we are going to move the entire part toward the ceiling a couple of inches.




Before we get started, create a PickPoint where the part is going to move to. This is not needed if a PickPoint is already at the new location.


Step 1) Select the "**Move Part**" command button:




Step 2) **Select ANY PickPoint on the part you are going to adjust.** We are only doing one thing with this step and that is to select the part. Select the easiest point to select the part.



Step 3) **Select the PickPoint on the part that will be the coupler location.** This will be the point of the part that is anchored to the cursor while it's being moved.



Step 4) Select the PickPoint the part is moving to.



Bend-Tech will relocate the part.

